Docket No.: 30365/39652

(PATENT)

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of: Michael L. Bolind et al.

Patent No.: 7,175,426

Issued: February 13, 2007

For: HIGH EFFICIENCY REFRACTORYLESS

KETTLE

REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.322

Attention: Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Sir:

Upon reviewing the above-identified patent, Patentee noted a typographical error which should be corrected.

In the Claims:

In the Amendment dated July 31, 2006, page 13, Claim 70, line 1, PTO error, please add -- 70. The method of claim 68, further comprising: removing and churning stagnant portions of gypsum adjacent the bottom wall with an agitation mechanism. --.

The error was not in the application as filed by applicant; accordingly no fee is required.

Patent No.: 7,175,426 Docket No.: 30365/39652

Transmitted herewith is a proposed Certificate of Correction effecting such amendment. Patentee respectfully solicits the granting of the requested Certificate of Correction.

Dated: March 5, 2008

Respectfully submitted,

Richard B. Hoffman

Registration No.: 26,910

MARSHALL, GERSTEIN & BORUN LLP

233 S. Wacker Drive, Suite 6300

Sears Tower

Chicago, Illinois 60606-6357

(312) 474-6300

Attorney for Applicants

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. 7,175,426

APPLICATION NO. : 10/788,871

February 13, 2007 ISSUE DATE

INVENTOR(S) Michael L. Bolind et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Claims:

At Column 10, line 66, please add -- 70. The method of claim 68, further comprising: removing and churning stagnant portions of gypsum adjacent the bottom wall with an agitation mechanism. --.